	sday, 11/29/2005 7:07:47 PM a Lacelle	cess Sheet				
ustomer ob Number stimate Number O. Number his Issue rist Issue revious Run Vritten By checked & Appro-	: NC : NC : NC : N/A : Type : SMALL /MED FAB oved By ; : Created By Auto Work Order	Drawing Name Part Number Drawing Number Project Number Drawing Revision Material Due Date	: JET TUBE : D2409 : D2409 REV. A : N/A : A : N/A : 12/11/2005	Qty:	5 Um:	Each
				-4-		÷
Job Number:					ener, energy	<u></u>
Seq.#.	Machine Or Operation:	Description :				
1.0	, de la	31-T6 Tube .500 x.035W			_	
Com	ment: Qty.: 1.6666 f(s)/Unit Total: 8.3330 f(s)					
	6061-T6 Tube 0.50 x .035W Material: 6061-T6 (0.50" OD x 0.035") wall sear (M6061T6T0.500W.035)	mless tubing M469 Batch: 14190	96	FFC	5.12	.05
1	Tools:	MALL & MEDIUM FAB RESOUR	PCE 1	, , , , , , , , , , , , , , , , , , , ,		
2.0	SMALL FAB 1 SM	MALL & WIEDION I AD INCOOR				`
Com	ment: SMALL & MEDIUM FAB RESOURCE 1	4- Flave to	ong ev end, e	Prope out	7	
	1- Cut as per template D2409T1 2- Deburr 3- Bend as per template D2409T2 & Dwg D240 Identify as D2409	09				
	Tools:		ATER	FF 05	17:0	2 6
3.0		ISPECT WORK TO CURRENT	STEP		06.05.10	5
	nment: INSPECT WORK TO CURRENT STEP					
4.0	Tools: PACKAGING 1 P	ACKAGING RESOURCE #1				
Cor	mment: PACKAGING RESOURCE #1 Identify and Stock Location:	A. T		Mog	05/	146
	Tools:					
			Ž.			

Page 1

Form; rprocess

3		16	9										•
		4		•		÷2	-	1	•				
<u> </u>		3	, Š.	7		164						÷	
Dart:	Ae	ro	Sp	a	Çе	LI	:a		٠,		1	-	
	7			٥	- 4	<i>'</i> •		•			- :		
	-	(2.7	-		.7		ć,	- 2			_

W/O:		S. S.	WORK OF	RDER CHANGES	ۏ		•		
DATE	STEP		PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
05-11-06	2:	Dong chi	Addinspect part.	ge Add Clance	n th	5 W/D 2060S	ر ا	Dan	W-1206
-	A STATE OF THE STA				\$ 4				

PAR #: NID Fault Category: Pod FRB ASS' Med Small NCR: Yes/No DQA: Part No: <u>Day 09</u>

Date: <u>C6/05/17</u>

NCR:		į į į	W	PRK OR	RDER NON-CONFORMANCE	(NCR)			1
<i>€</i> #	(-)	Description of NC Corrective Action Section B		Verification	Approval	al Approval			
DATE	DATE STEP Description Section				Action Description ief Eng Chief Eng		Section C	Chief Eng	QC Inspector
05-12-66		5x 02409 were made of .500 x .035 SS tubing, 80 "		Barn	SCVAP And clostroy mat/ And lesse replace with Al. As per Dwg Dayog and I.P.P. Instructions. Ensure employee understands the type of material neecled.	05.1206	US-n-06	Bush	05-12-06
			· · · · · · · · · · · · · · · · · · ·	20 T T T T T T T T T T T T T T T T T T T		# 1			
			To make an about the second se					.• '	

Date: User: Tuesday, 11/29/2005 7:07:47 PM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: JET TUBE

Job Number: 25065

Part Number: D2409

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

DC

DOCUMENT CONTROL

D06/05/17

Comment: DOCUMENT CONTROL Inspection Level 21

Tools:

Job Completion




U 06.05.17


Dart Ae	rospace	e Ltd	• · · · · · · · · · · · · · · · · · · ·				en e en	ere se is			• •		~
W/O:				<u>.</u>		W	ORK ORDER CHA	ANGES					
DATE	STEP	1		7. J	PROC	EDURE CHA			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approv. QC Inspect
To a second seco	The special state of the speci	The state of the s			•								
5	Topic of the control	2		The second secon		W. C.							
Part No	»:		Р	AR #: _		_ Fault Cate	gory:	NC	R: Yes	No DQ	A:	Date:	
4 •	•	1		· •					QA: N	I/C Close	d:	_ Date: _	
NCR:				¥	W	ORK ORD	ER NON-CONFO	RMANCE	(NCF	₹)	****		
		į į	Description	of NC			Corrective Action	Section B	Verification			Approval	
DATE	STEP		Section			Initial Chief Eng	Action Descript Chief Eng	tion	Sign 8 Date	Secti		Chief Eng	Approva QC Inspect
		1		,									
•	į	1											
4		1											, ,
*		5	The state of the s				-						1

NOTE: Date & initial all entries



PREPARED B. William	s		ACCESSORIES INC	
CHECKED BW	APPROVED	D2409	REV. SHEET 1 OF	A 1
DATE		TILE	SCAL	E
Apr. 6, 1	995	JET TUBE	1:	:2





MATERIAL: 0.50 OD 0.035 WALL AL BEND PER TEMPLATE TD2409